

1

2

3

4


5

6

CLAMPING INSERTS FOR MACHINE VISES

■ Prism inserts for horizontal and vertical clamping of round workpieces, hardened and ground

Code No.	S	L1	L2	L3	L4	L5	D	D1	Clamping range Ø vertical		Clamping range Ø horizontal	For Type
									d1	d2	d3	
									[mm]			
7-290-204	100	32.4	18	70	20	14.8	9	15.0	4-9	8-51	6-35	6512, 6530, 6537
7-290-205	125	40.0	22	85	25	18.6	11	18.0	5-12	11-71	4-45	6512, 6530, 6537
7-290-206	160	50.4	24	110	31	20.6	11	18.0	6-16	14-95	9-57	6512, 6515, 6516, 6522, 6530, 6537
7-290-208	200	63.0	30	140	40	25.0	14	20.0	7-20	18-123	12-75	6512, 6515, 6516, 6522, 6537
7-290-210	250	80.0	35	160	32	29.0	17	26.5	10-27	20-138	15-98	6512, 6537
7-290-2050	125	42.0	22	89	25	18.6	11	18.0	5-12	11-71	4-45	6515, 6516




1-pc/set

CLAMPING INSERTS FOR MACHINE VISES

■ Prism inserts for horizontal and vertical clamping of round workpieces, hardened and ground

Code No.	S	L1	L2	L3	L4	D	Clamping range Ø vertical		Clamping range Ø horizontal	For Type
							d1	d2	d3	
	[mm]									
7-292-204	100	32.4	18	63	14.0	M8	4-9	8 -51	6-35	6517. 6518
7-292-205	125	40.0	22	80	15.8	M10	5-12	11 -71	7-45	6517. 6518
7-292-206	160	50.4	24	100	20.0	M10	6-16	14-95	9-57	6517. 6518
7-292-208	200	63.0	30	125	25.0	M12	7-20	18-123	12-77	6517. 6518




1-pc/set

CLAMPING INSERTS FOR MACHINE VISES

■ Inclined inserts for horizontal clamping of round workpieces, hardened and ground

Code No.	S	L1	L2	L3	L4	L5	D	D1	Clamping range Ø horizontal	For Type
	[mm]									
7-290-044	100	32.4	18	70	14	14.8	9	15	8-30	6512, 6530, 6537
7-290-045	125	40.0	22	85	17	18.6	11	18	12-38	6512, 6537, 6530
7-290-046	160	50.4	24	110	20	20.6	11	18	14-48	6512, 6515, 6516, 6522, 6530, 6537
7-290-048	200	63.0	30	140	28	25.0	14	20	18-61	6512, 6515, 6516, 6522, 6537
7-290-0450	125	42.0	22	89	18	18.6	11	18	12-38	6515, 6516



1-pc/set